


**Please note:**

HANDLE MUST BE ON THE OUTER SIDE OF THE LIFT



The positioning of the power pack - left/right side compared to the lift - is optional.

Date: 080109 Sign. LJE  
 Update:  
 STENHØJ AUTOLIFT A/S  
 E-mail: salg-dk@stenhoj.dk  
 FAX: +45 76 82 13 31



**STENHØJ**

No. T11347

Marshal 3000S